

310 MEETING AGENDA

1. Meeting Called to Order
2. Public Comments on District 310 Permitting Business
3. 310 Inspection Reports: Ready for Discussion and Board Decision

Application Number: GD 76-18 Inspection Date: 12/11/2018
Applicant: Matt Skoglund
Landowner: Matt Skoglund, Skoglund Ranch LLC
Contractor/Agent: Gary Hillman
Perennial Stream: UT to Middle Fork of Dry Creek
Type of Project: New water pipeline from existing well to new stock tank
Purpose: The purpose of the project is to put a new geothermal stock tank in our welcome/training pasture to (1) limit our bison's access to the riparian area and (2) to provide consistent water 365 days a year.
Proposed Construction Date: Start date: 12/22/2018 Finish date: 1/15/2019
Inspection Recommendation: Approval as proposed
Inspection Comments: Minimal impact to stream – boring under creek, culvert is to prevent infiltration into boring. Culvert will be laid without disturbance to bed/bank, potentially some dressing at inlet/outlet to prevent flanking. No fill over culvert is proposed. Good conservation project.

Application Number: GD 77-18 Inspection Date: 12/11/2018
Applicant: Flanders Mill, LLC; Walter Wolf
Landowner: City of Bozeman and Bozeman High School District 7
Contractor/Agent: Lynn Bacon, TerraQuatics, LLC
Perennial Stream: Maynard-Border Irrigation Ditch
Type of Project: Ditch Bed Maintenance; Placement of Fill (in OHWM)
Purpose: To manage rehabilitation of ditch bed.
Proposed Construction Date: Start date: December 21, 2018 Finish date: 5/31/2019
Inspection Recommendation: Approval as proposed
Inspection Comments: Jurisdictional reach begins at drain ditch culvert outlet and north to Baxter (and onward). Drain ditch source is groundwater from north of the substation on east side of Flanders Mill Road.

4. 310 Old Business: REVISED Applications (previously placed on hold)

Application Number: GD 68-18 Inspection Date: 10/9/2018
Applicant: Legends II at Bridger Creek HOA
Landowner: Legends II at Bridger Creek HOA
Contractor/Agent: Not provided
Perennial Stream: Bridger Creek
Type of Project: Removal of beaver dam
Purpose: Reduce the damage from a beaver dam causing premature flooding that has and is continually causing damage to the trail and destabilizing the creek bank.

Proposed Construction Date: Start date: 11/30/2018 Finish date: 3/31/2019
Inspection Recommendation: **On Hold**
Inspection Comments: Hold for one month to agree on solid direction from applicant.

Revised Application:

Purpose: Repair damage to neighborhood trail system caused by flooding during spring 2018. Project will include:
1. Breaching or completely removing two beaver dams that were constructed in early summer 2018 that are causing over bank flooding along neighborhood trail system.
2. Repairing damaged trail segment by filling and re-vegetating scour hole formed during spring flooding.

Proposed Construction Date: Start date: 2/1/2019 Finish date: 3/31/2019
Inspection Recommendation: Approval as proposed
Inspection Comments: Prefer handwork to machine due to access challenges to vegetation damage to breach dams. If those efforts are not successful, equipment may be used with minimal impacts while accessing. Watch during runoff and assess afterwards. Removal of historic dam not in this application.

Application Number: GD 70-18: Inspection Date: Not re-inspected
Applicant: Robert K Shepherd
Landowner: Robert K Shepherd
Contractor/Agent: Tom Henesh, Big Sky Land Consulting, Inc.
Perennial Stream: West Gallatin River
Type of Projects: Bank Stabilization/Alteration; Flood Protection

Gallatin Conservation District Meeting Agenda

December 20, 2018
9:00 am

Purpose: Protect existing usable land from being washed away and turning useable upper land into river bottom. Install Class III Riprap with geotextile fabric along east bank of West Gallatin River with trees.

Proposed Construction Date: Start date: 11/20/2018 Finish date: 12/20/2018

Inspection Recommendation: Approval with modifications

Inspection Comments: Large degree of change following runoff. Skinny parcel with temporary cabins on low ground, river aggrading to similar elevation. Rock is last effort to save property. Concern over ending short on downstream from absentee landowner. Very deep at downstream end. Incorporate wood root wads/trunk matrix into bank treatment.

Board Decision: **On Hold**

Revised Application:

Application Number: GD 70-18: Inspection Date: Not re-inspected

Purpose: Install Class III riprap with tree stump root ball mass along with geotextile fabric along the east bank of the West Gallatin River along with new trees.

Proposed Construction Date: Start date: 1/20/2019 Finish date: 4/30/2019

Inspection Recommendation: None

Inspection Comments: None

5. 310 Emergency Applications: None

6. 310 New Business: None

7. Adjournment of 310 Meeting

BUSINESS MEETING AGENDA

1. Guests & Public Comments on District Business Meeting
2. Grants/Agreements/Contract Report
3. Consensus Agenda
 - a. November Meeting Minutes
4. NRCS
 - a. Report
5. Supervisor Report: Planning Boards
6. Old Business
7. New Business
 - a. Why Choose to serve with CDs?
8. Well-Testing Cost-share Program: None
9. Cost-share Program: None
10. CD Seminars/Workshops: None
11. Correspondence and Handouts
 - a. Mileage report
12. Accounting (Deposit, Credit Card, Invoices) + Updated P&L, Balance Sheet
13. Adjournment of Meeting